





FIG. 1



F I G. 2

F I G. 3A**F I G. 3B**


F I G. 4





FIG. 5

FIG. 6



F I G. 7

F I G. 8

T 00850 = 0059960

FIG. 9

PROBLEMS OF COMPUTER

URL <http://www.maintain.co.jp/db/input.html>

TROUBLE DB INPUT WINDOW

OCCURRENCE DATE 404

TYPE OF APPARATUS 401

SUBJECT 403

APPARATUS S/N 402


DEGREE OF URGENCY 405

SYMPTOM 406

REMEDY 407

PROGRESS 408

410 411 411 412 412

F I G. 10

SEMICONDUCTOR DEVICE MANUFACTURING FLOW

FIG. 11

